



## Sanitary Sewer Overflow (SSO) Report to PADEP

1. Date, Name, Phone # of person completing this report	Date : 4/10/14 Name : John Nyemscek Phone # 610-437-7646 Signature: 
2. Your organization name and address ?	Lehigh County Authority Water Resources Distribution/Sewer Line maintenance 1242 Martin Luther King Jr. Dr., Allentown Pa
3. Date found and <u>specific</u> location of SSO ?	Found on 4/10/14 behind the WAWA Gas Station at 2209 Lehigh St., Allentown, PA. At manhole number 32_34E . See attached map
4. How was SSO discovered? By who ?	The SSO was discovered by a building contractor working next to WAWA.
5. Start and end time of SSO (actual or estimate?)	Estimated start time 8:00 AM 4/10/14 - end time 9:00 AM 4/10/14.
6. Date, time and name of person who notified PADEP of SSO ?	Date : 4/10/14 Time : 10:55 AM Name : John Nyemscek
7. Description and actual or estimated volume of SSO	Small Overflow; estimated volume 10 gallons.
8. Where, <u>precisely</u> , did SSO go ? (land, roadway, basement, swale, storm sewer, creek, etc)	The SSO was contained to an area aproximately 5' x 5' around manhole 32_34E in the grass.
9. What caused SSO ? How was it stopped ?	Jetting and vacuuming.
10. Describe extent of contamination and how it was cleaned up	The contamination was removed and the affected area was covered with lime.
11. What actions will be taken to prevent a re-occurrence ? When ?	Periodic checks will be applied to this particular sanitary segment.
12. Other comments ?	

← N



**Lehigh County Authority**

This map was produced from LCA's Geographic Information System. LCA expressly disclaims any liability that may result from the use of this map. Copyright © LCA. All rights reserved. Printed on 4/10/2014

